


CDC-X1750M YL CDC-X175M YU CDC-X155M YU



SERVICE MANUAL

STEREO CAR CD RECEIVER

BASIC CD MECHANISM: SCD-333A

This Service manual contains information about correction on Service manual of CDC-X1750M<YL>/CDC-X175M<YU>/CDC-155M<YU>(S/M Code No. 09-989-270-2S1).





ELECTRICAL PARTS LIST 1/1

TRUE

REF. NO		NRI O.	DESCRIPTION	REF. NO	PART NO.	KANI NO	
TRANSISTOR					R		
	87-026-236-080 87-026-239-080		4EKA-T146 4TKA-T146		87-026-239-08 87-026-236-08		TR,DTC124EKA-T146 TR,DTC114TKA-T146
DIODE	87-017-366-080	DIODE, DA	N202U	DIODE	87-026-239-08	0	DIODE, DAN202U
CD C.B				CD C.B			
D630 D631 D632	98-729-052-250 98-729-052-250 98-729-052-250	DIODE, CL	-2001R-X-TU-BC -2001R-X-TU-BC -2001R-X-TU-BC	D630 D631 D632	S1-305-700-28 S1-305-700-28 S1-305-700-28	6	DIODE, CL-2001R-X-TU-BC DIODE, CL-2001R-X-TU-BC DIODE, CL-2001R-X-TU-BC

FALSE

アイワ株式会社〒110-8710 東京都台東区池之端1-2-11 ☎03(3827)3111 (代表) **AIWA CO.,LTD.**2-11, IKENOHATA 1-CHOME, TAITO-KU, TOKYO 110, JAPAN TEL:03 (3827) 3111

920074 Printed in Singapore